

PAS 250 MK2 PODIUM UNIT ASSEMBLY GUIDE(FIXED STABILISERS)




Dimensions — Platform at 1.5M x Width -0.85M x Depth 1.3M
Working Height — 3.5M (Max)
Dimensions — Folded Height -2.5M x Width - 0.25M x Depth - 1.3M
Weight—42kg Safe Working Load - 150kg
Manufactured under an ISO9001:2008 Quality System
Complies fully with the Working at Height Regulations 2005 and PAS250
Specifications
Lightweight all Aluminium Construction

PAS 250 MK2 PODIUM UNIT ASSEMBLY GUIDE (FIXED STABILISERS)



1 X FOLDING FRAME
1 X PLATFORM
1 X DIAGONAL BRACE
1 X LADDER



1) OPEN FRAME AND LOCK
MECHANISM



2) FIT PLATFORM AT
CORRECT HEIGHT



3) FIT DIAGONAL BRACE



4) CLIP UPPER BRACE
OF LADDER ABOVE
RINGS ON VERTICALS
WITH ASSEMBLED
HOOKS ON TOP



5) POSITION UNIT AND LOCK
CASTORS



6) DEPLOY STABILISERS IN
CORRECT POSITION




7) USE LADDER TO
ACCESS PLATFORM




8) CLOSE AND
LOCK GATE


IMPORTANT SAFETY NOTES




ALWAYS READ THE INSTRUCTIONS
BEFORE USING PODIUM




NEVER USE A PODIUM WITH
DAMAGED OR MISSING COMPONENTS




NEVER OVERREACH




NEVER HAVE MORE THAN ONE
PERSON ON THE PLATFORM




NEVER USE ON UNEVEN
OR SLOPING SURFACES




DO NOT MOVE PODIUM IF A
PERSON IS STILL ON IT




NEVER USE BOXES FOR EXTRA
HEIGHT, STAND ONLY ON THE PLATFORM



NEVER USE PODIUMS AS A MEANS
OF ACCESS TO ANOTHER PLACE.



NEVER USE PODIUMS NEAR
ELECTRICAL POWER LINES



ALWAYS LOCK ALL CASTORS WHEN
PODIUM IS SITED, AND BEFORE USE.

BE AWARE OF THE FOLLOWING:-

- A. DO NOT USE ON LOOSE OR SLIPPERY SURFACES.
- B. NEVER STAND ON THE ACCESS LADDER TO WORK.
- C. WORKING PLATFORM MUST BE LEVEL.
- D. INSPECT BEFORE USE.
- E. ONLY ASCEND OR DESCEND THE LLWP USING THE ACCESS PROVIDED.
- F. FACE THE FOLDING BACK SECTION WHEN ASCENDING OR DESCENDING.
- G. ENSURE THE GATE IS CLOSED AND LOCKED BEFORE USE.
- H. BEWARE OF FINGER TRAPS.
- J. TO MOVE UNIT UNLOCK GATE AND DISMOUNT, UNLOCK CASTORS AND RE-LOCATE.
- K. IF IN DOUBT DO NOT GUESS CONSULT YOUR SUPPLIER.
- L. SEE OVERLEAF FOR COMPONENT CHECKLIST